



Photo 1: West breakwater looking west



Photo 2: East breakwater looking east from damaged section



Photo 3: Beach E



Photo 4: Beaches and Prince George Wharf



Photo 5: Beaches looking west to Arawak Cay warehouse




Photo 6: Beaches looking west to Arawak Cay warehouse



Photo 7: Eastern entrance channel with damaged breakwater and Paradise Island lighthouse



Photo 8: Residences on Paradise Island (south side) near dredge area 5



Photos from left to right. At Dredge Area 1; 9. *Halimeda* amongst the Turtle grass. 10. Conch next to Finger coral. 11. *Rhipocephalus phoenix*.)




Photo 12 at Dredge Area 2. Gold spotted eel hunting a crab amongst the Turtle grass. *Laurencia*, *Halimeda* and other alga.

Photo 13 at Dredge Area 2. Mermaid's fan with some Feather duster worms in front and some *Laurencia* (brown alga) in the back.)

